



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Internal

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

October 4, 1999

TO: Minerals File

FROM: Lynn Kunzler, Senior Reclamation Specialist *LK*

RE: Site Inspection, Young Stone Supply, Inc. Young Browns Canyon Quarry, S/043/019, Summit County, Utah

Date of Inspection: September 15, 1999
Time of Inspection: 8:00 a.m.
Conditions: Clear, cool
Participants: Jon Young, Operator; Lynn Kunzler and Doug Jensen, DOGM

Purpose of Inspection: To document site conditions.

This inspection was conducted at the request of the operator. Concerns were expressed that the quarry was expanding beyond the 5 acre threshold for a small mining operation.

Upon arrival at the site, a GPS unit was set up as a base station and a second unit was used to map the disturbed areas. Disturbance included the main quarry area and parking, a storage area, and an access road between the two sites.

We discussed with the operator that it appeared that his disturbance was close to, if not exceeding 5 acres and his options would be to either permit the site as a large mining operation or reclaim a portion of the site. The results of this survey showed 5.1 acres of disturbance. Given the margin of error of our GPS, enforcement action is not warranted at this time. However, the operation must not expand without first reclaiming a portion equal to the proposed expansion or, permitting the site as a large mining operation.

The site was active during the inspection with no other problems being noted. The site appeared to be free of garbage and debris and no off-site impacts were noted.

Several photos were taken to document site conditions.

m043019.ins

0001